


NOTE:
STANDOFF BRACKET LOCATIONS

ARE +/- 1"

DO NOT PREDRILL HOLES IN THE STRUCTURE.
HOLES SHOULD BE MATCH DRILLED TO ENSURE
ALIGNMENT.

3D MODEL AVAILABLE IN STEP FILE FORMAT ON OUR WEBSITE

| | | | | |
|---|------------|--|---|--------------|
| DRAWN GG | 12/28/2016 |  Division of Material Control, Inc. 130 Seltzer Road, Croswell, Michigan 48422 U.S.A. | | |
| CHECKED | | | | |
| APPROVED | | TITLE | | |
| PART D0570348 F34S FOR CATALOG | | F34S | | |
| THIS PRINT IS PROPERTY OF COTTERMAN® COMPANY, AND MAY NOT BE USED IN WHOLE OR PART WITHOUT WRITTEN PERMISSION. | | Drawing is computer generated, and print might not be to scale | | |
| | | SIZE C | DWG NO D0570348 F34S FOR CATALOG.dwg | REV A |
| | | DIMENSIONS IN INCHES UNLESS NOTED | | |
| | | | | SHEET 1 OF 1 |